
Subject: Aw: Kenwood TH-79 Handfunkgerät
Posted by [Anode](#) on Fri, 02 Nov 2012 22:11:09 GMT
[View Forum Message](#) <> [Reply to Message](#)

Unter <http://vss.pl/mods.dk/mods.php3-radio=kenwood&model=th-79&selectid=2212.htm> findet man folgendes:

7.6 display contrast problems ?

There are often contact problems between the main board and the display. To fix the problem fasten the screws at the backside of the display. Now the display should work again. You can lock the screws with some nail-paint for example.

Der Fehler scheint also in den meisten Fällen durch Kontaktprobleme zwischen Hauptplatine und Display verursacht zu sein. Ursache kann wohl auch die Flexleitung im Gerät sein. Hast Du diese Verbindungsleitung schon überprüft?

Viele Grüße, Dirk